

DRAFT

Appendix E

Photolog



DRAFT



Wetland 1, vegetation typical.



Wetland 1 edge, abrupt change between wetland and upland vegetation.



Wetland 2 interior.



Wetland 3, abutting S 320th Street; photo oriented facing east.



Wetland 5 interior; photo taken at SP-8.



Wetland 6; located between two developed land parcels.



Wetland 7; photo oriented facing north.



Wetland 9, vegetation typical.



Wetland 10; photo taken at wetland inlet oriented facing south.



Wetland 11 interior.



Wetland 12.



Wetland 13; photo oriented facing west on S 320th Street.





Wetland 14, vegetation typical.

No photo for Wetland 15



Wetland 16, interior vegetation structure.



Wetland 17 interior; photo oriented facing south.



Wetland 18 interior.



Wetland 19.



Wetland 20; facing north. Water drainages visible.